



1/14

FIG. 1



2/14

FIG. 2



3/14

FIG. 3




FIG. 4A

SENSITIVITY LIMIT OF X,Y,Z DIRECTIONS (mm)





FIG. 4B



4/14

FIG. 5






FIG. 6




5/14

FIG. 7




6/14

FIG. 8




7/14

FIG. 9




8/14

FIG. 10




9/14

FIG. 11




10/14

FIG. 12




11/14

FIG. 13




12/14

FIG. 14






13/14

FIG. 15



14/14

FIG. 16

LAYOUT OF BUTTONS	AVE. OF OPERA- TION TIME	SUBJECTIVE EVALUATION
<p>①</p> 	46.4sec	0
<p>②</p> 	43.2sec	6
<p>③</p> 	43.2sec	9